


Power plant. 1 loop $\frac{3}{16}$ flat.



All formers made from $\frac{1}{16}$ sheet. And all stringers $\frac{1}{16} \times \frac{1}{16}$ balsa.

Pants may be made in one or two pieces. A 1" wheel is used.

Sheet 5

Aviata Zier

STINSON RELIANT—Sheet 5

[55]